

WS 5A-DA

END STRIPPER WITH DRILL ADAPTER

Warning! This tool should not be used on live electrical circuits! Always use OSHA/ANSI or other industry approved eye protection when using tools. This tool is not to be used for purposed other than intended. Read carefully and understand instructions before using this tool.

1. Read WS5A tool instructions for full understanding of the basic tool's features and operation. Select the proper WS-5 bushing for the cable being prepared. Adjust the tool and bushing as described in those instructions.
2. Manually, make a test cut on the cable with the tool. Observe cable. Blade must not contact or score conductor. Re-adjust blade if necessary.
3. The WS5A-DA includes a drill adapter attachment for convenient power operation. The adapter attaches to the WS5A tool by means of a bayonet slot design. Push and turn to lock in place or detach.
4. Attach tool to variable speed drill. Run at low RPM's for best results.

WARRANTY: RIPLEY warrants its products against defective materials and workmanship for a period of one year from date of shipment from the RIPLEY factory provided the product is utilized in accordance with instructions and specified ratings.



46 Nooks Hill Road, Cromwell, CT 06416 USA ~ Phone: 800-528-8665 ~ Int'l: (01) 860-635-2200
Fax: (01) 860-635-3631 ~ E-mail: info@ripley-tools.com ~ Internet: www.ripley-tools.com



38715 rev1 12-01-12 ff

2 up copy